

BRIHANMUMBAI MAHANAGARPALIKA

No. Dir/ES&P/328/TAC dt. 10.08.2017

CIRCULAR

Sub: Action to be taken against the registered Structural Consultants those who are not complying the directions and circulars issued by Director (ES&P), Chairman of TAC while submitting structural audit report to Ward/TAC

Ref:- Hon'ble M.C.'s approval u/no. MGC/F/4225 dt.09/08/2017

Whenever the registered structural consultant /Engineer does not submit the structural audit report as per the direction of TAC or requirement of N.D. tests etc in prescribed proforma 'B'(Circular u/no. Dir/E.S.&P/51/III dated 27.05.2014), in that case:-

1. Show-cause to be issued to such Structural Consultants by Asstt. Commissioner for not submitting the N.D. tests result along with proforma 'B' duly signed on each and every page, as prescribed by TAC, with time period of 15 days. After 15 days from issuing the show cause notice, if they do not submit the same, the report should be sent to the Dy.Ch.Eng.(B.P.) City for non compliance.
2. Dy.Ch.Eng.(B.P.) City to initiate action against such structural Consultants/ Engineer's with approval of Dir(E.S&P) through Ch.Eng (D.P).
3. After 15 days from issuing show cause notice, Asstt. Commissioner should appoint structural consultant who is registered with MCGM and get structural audit report, within a month along with N.D. Tests and proforma 'B' duly signed on each and every page. The charges for such structural audit should be recovered from owner /tenants, whose structural consultant has not responded as per Point No.1. Further if Structural consultant of both owner or tenant are not responding, the charges should be recovered from both by dividing equally. After compliance, Asstt. Commissioners should take the action as per order's in W.P.No.1135 of 2014 for further processing the proposal.

However, in the meantime concerned Asstt. Commissioners are hereby directed to inform the owners /occupiers and structural auditor to take necessary preventive measures such as propping etc. to avoid any untoward incident.

The above said direction should be implemented by all H.O.Ds / Asstt. Commissioners concerned scrupulously.

Sd/-

09.08.2017

V.P. Chithore

Director(E.S.&P)

Chairman

Technical Advisory Committee

Asstt. Comm. - 'A' / 'B' / 'C' / 'D' / 'E' / 'F/S' / 'F/N' / 'G/S' / 'G/N' / 'H/E' / 'H/W' / 'K/E' / 'K/W' / 'L' / 'M/E' / 'M/W' / 'N' / 'P/S' / 'P/N' / 'R/S' / 'R/C' / 'R/N' / 'S' / 'T' Ward / Asstt. Comm. (Market) / A.C.Estate/Ch.Eng.(B.M.)/ **C.E**/Ch.Eng. (D.P.)/C.F.O./ H.E./ C.A.(Finance)/Ch.Eng.(W.S.P.)/Ch.Eng.(S.O.)/Ch.Eng.(S.P.)/Ch.Eng.(MSDP)/ Dy.C.E.(S.I.C.)/Dy.C.E. (H.I.C.)/M.A./E.E.(H.O.)

Copy to : D.M.C. (Zone-I / II / III / IV / V / VI / VII) / D.M.C. (Spl.) / D.M.C. (Imp.) / Law Officer / D.M.C. (A & C) / D.M.C. (Garden) / D.M.C. (CPD) / D.M.C. (R.E.) / D.M.C. (Env.) / D.M.C. (MCO)

Copy to : A.M.C. (W.S./ City/ E.S.)

Madam/ Sir,

For information please.

बृहन्मुंबई महानगरपालिका
नगर अभियंता
मध्यवर्ती कार्यालय

11 AUG 2017

वेळ ११, १२, १३, १४
१५, १६, १७, १८

१०१६३

EE(P)

pl. receipt handy

21/8/2017

Sd/-

09.08.2017

V.P. Chithore

Director(E.S.&P)

Chairman

Technical Advisory Committee